

## **RESOLUTION OF COMPLEX CLAIMS**

**Monica Van der Merwe** 



## **Lorca Consulting**

Lorca Consulting was established in October 2017. As a consulting firm we offer support and expert advice to Clients relating to Scientific investigation and Analysis methods in a variety of Industries.

With 20 years' experience in the Analytical Chemistry industry, we pride ourselves in providing quality Analytical results substantiated by acclaimed international published research papers.



## SOP

# Lorca Consulting their approach with all assessments on the Scientific method:

"The scientific method is an <u>empirical</u> method of acquiring <u>knowledge</u> that has characterized the development of <u>science</u> since at least the 17th century (with notable practitioners in previous centuries). It involves careful <u>observation</u>, applying rigorous <u>scepticism</u> about what is observed, given that <u>cognitive assumptions</u> can distort how one interprets the <u>observation</u>. It involves formulating <u>hypotheses</u>, via <u>induction</u>, based on such observations; <u>experimental</u> and measurement-based testing of <u>deductions</u> drawn from the hypotheses; and refinement (or elimination) of the hypotheses based on the experimental findings. These are *principles* of the scientific method, as distinguished from a definitive series of steps applicable to all scientific enterprises."



## **Failure Analysis**

# Failure analysis is a systematic investigative procedure using the scientific method to identify the causes of a failure.

- ASM methodology is applied to conduct failure analysis where appropriate.
- The Failure Analysis Society is the newest affiliate society from ASM International. Founded in 2016, this society is dedicated to advancing the important role failure analysis plays in the materials science industry.
- The Failure Mode and Effect Analysis (FMEA) Process is followed. The FMEA methodology is based on a hierarchical, inductive approach to analysis.



#### TEST METHODS FOR RESOLUTION OF COMPLEX CLAIMS

Scientific Method Sampling Witness statements Benefits of testing

#### **TYPES OF TESTING**

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

PRE-LOSS

INDUSTRY APPLICATION

REPORTING

## Introduction

- Different Scientific disciplines
- Binding factor for Integrated approach
- Scientific method
  - Holistic approach (Outside-In approach)
  - Survey to obtain the big picture = Test plan
  - Record keeping, photographic and video evidence (application to make use of drone technology) i.e. Conceptual map





#### TEST METHODS FOR RESOLUTION OF COMPLEX CLAIMS

Scientific Method Sampling Witness statements Benefits of testing

- Sampling
  - On-site gathering of physical evidence
  - Samples are specific to Analytical Techniques
  - Correct amount and type of sample for specific application
  - Destructive/Non-destructive testing
    - Physical testing
    - Wet Chemistry
    - Instrument analysis



TEST METHODS FOR RESOLUTION OF COMPLEX CLAIMS

> Scientific Method Sampling Witness statements Benefits of testing

#### • Witness statements

- Corroborate with evidence on scene?
- Human error
  - Corruption
  - Error in observation
  - Pre-conceived Bias
  - Stress (traumatic event)



Vector**Stock**®

VectorStock.com/19038682

#### TEST METHODS FOR RESOLUTION OF COMPLEX CLAIMS

Scientific Method Sampling Witness statements Benefits of testing

## • Benefits of Testing

- Physical evidence Proof
- Accountable and ethical approach
- Loss adjusting tool
- Fair settlement of the claim



Identify factors to consider in pre-loss assessments in future

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

## **Types of Testing**

#### Non-Destructive methods

- Physical investigation
- Photography, Microscopy
- Thermal Imaging
- RAMAN Spectroscopy (Portable)
- X-Ray Analysis (XRF Hand Held)

## **Destructive testing**

- Electron Microscopy (SEM, TEM, EDX, EDS)
- Spectroscopy (FTIR and Imaging Analysis)
- Organic Contamination (TOC, COD)
- X-Ray Analysis (XRF, XRD)
- Emission Spectroscopy (OES, NMR)
- Oil Analysis





Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

## **Thermal Imaging**

- Identify thermal anomalies that can indicate possible defects
- Create a baseline determine a maintenance schedules for fault identification
- Used for electrical, mechanical and building applications, offshore oil and gas platforms as well as detecting leaks and moisture issues
- Non-contact and non-destructive
- Our thermal imaging technicians are all certified ITC thermographers
- Pre-loss tool



![](_page_12_Picture_10.jpeg)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

## Wet Chemistry

- Residue testing
- Oil Analysis (TBN, TAN)
- Fuel Analysis
- Chemical Identification
- Viscosity, Turbidity, pH
- Melting Point

![](_page_13_Picture_9.jpeg)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

#### **Instrument Analysis**

- Microscopy
- Electron Microscopy (SEM, TEM)
- X-Ray Analysis (XRF, XRD)
- Spectroscopy Analysis (FTIR, RAMAN)
- Chromatography (GC, HPLC, Headspace)
- Spectroscopy (ICP, ICP-MS) metal analysis
- Organic Contaminants (TOC, COD, BOD)

![](_page_14_Picture_10.jpeg)

![](_page_15_Picture_0.jpeg)

![](_page_16_Picture_0.jpeg)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

#### **Fire Investigation**

- Physical observation
- Analysis of hydrocarbons (FTIR) for Wet smoke detection
- Dry smoke detection effect on substances
  - SEM analysis
  - Gas analyser (sniffer probe)
- Effects of heat of combustion
  - Analysis for propellants (FTIR)
  - SEM analysis
  - Melting point of specific metals
- Analysis of char, ash and soot (SEM/EDX and pH)

![](_page_16_Picture_13.jpeg)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

## Lightning vs. Surge

- Analysis of damage on PCB's using SEM comparative methods
- Microscopy
- XRF
- Curve Analysis On-site

![](_page_17_Picture_7.jpeg)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

#### Product failure

#### Metals

- Chemical verification (SEM and ICP MS)
- Contamination analysis (OES, XRF, SEM)
- Corrosion analysis (SEM, Microbiological testing)
- Macro etching (SEM/EDX)
- Micro structure evaluation (SEM/EDS)
- Photo Documentation (Microscopy)
- Physical testing
- Surface contamination and weld evaluation (SEM and FTIR analysis)
- Solder failures and PCB contamination (SEM/EDX and FTIR)

Thermal imaging Wet Chemistry Instrument analysis Transformer testing Fire Investigation Lightning vs. Surge Product failure

#### **Product failure**

Non-Metals (Plastics, Composites, Adhesives, Coatings and Paint)

- Adhesive identification (FTIR)
- Coating contamination (Lab Analysis and FTIR)
- Paint identification (RAMAN, Physical testing and Photo documentation)
- Filter assemblies
- Fibre identification (SEM)
- Plastic fatigue (Physical testing)
- Visual defects
- Plastic weld failures

### Case study – Connecting Rod Failure

- Scenario Help identify a possible crack vs. fatigue
- Samples were prepared and SEM analysis performed

![](_page_20_Picture_3.jpeg)

![](_page_20_Picture_4.jpeg)

![](_page_20_Picture_5.jpeg)

![](_page_20_Picture_6.jpeg)

### Case study – Connecting Rod Failure

![](_page_21_Picture_1.jpeg)

Image typical crack

![](_page_21_Picture_3.jpeg)

#### Image typical fatigue

![](_page_21_Picture_5.jpeg)

Fatigue striations (Actual sample)

![](_page_22_Picture_0.jpeg)

![](_page_22_Picture_1.jpeg)

#### Result

- With the help of SEM analysis metal fatigue and strain became visible
- More fatigue and even burn marks were identified exact point of strain on chamfer identified
- Fatigue and strain pointed to the cause of the failure
- Determine metal composition and distribution

#### Case study – Damage in transit vs. Product failure

- Scenario Identify possible damage in transit
- Microscopy, FTIR and XRD analysis performed

![](_page_23_Picture_3.jpeg)

![](_page_23_Picture_4.jpeg)

![](_page_23_Picture_5.jpeg)

#### Case study – Damage in transit vs. Product failure

![](_page_24_Picture_1.jpeg)

![](_page_24_Picture_2.jpeg)

![](_page_24_Picture_3.jpeg)

#### Microscopic/Visual Analysis

#### Case study – Damage in transit vs. product failure

- Typical Cement composition:
  - CaO, SiO<sub>2</sub>, Al<sub>2</sub>O<sub>3</sub>, and Fe<sub>2</sub>O<sub>3</sub>
- Oxides in smaller quantities:
  - $SO_3$ , MgO, Na<sub>2</sub>O, and K<sub>2</sub>O
- Analysis indicated absence of Aluminium Oxides
- Water content ratio incorrect
- Not homogeneous

Result was Manufacturing issue, lack of QC and inferior quality of the product

![](_page_25_Picture_9.jpeg)

**Bruker AXS D8 XRD Instrument** 

#### Case study – Harvester Fire

#### Scenario - Determine possible cause of Harvester Fire

- Spontaneous combustion
- Product failure
- Maintenance Issues

![](_page_26_Picture_5.jpeg)

![](_page_26_Picture_6.jpeg)

![](_page_26_Picture_7.jpeg)

#### Case study – Harvester Fire

#### Test plan – Residue identification and Analysis

- Microscopy
- FTIR Analysis

![](_page_27_Picture_4.jpeg)

![](_page_27_Picture_5.jpeg)

![](_page_27_Picture_6.jpeg)

#### Case study – Harvester Fire

![](_page_28_Figure_1.jpeg)

#### **Result – Contamination**

- Samples collected from both the Radiator and Hydraulic system indicated the presence of polysaccharides, sugars and plant material
- Engine Contamination

#### Case study – Underground fuel storage tanks

Scenario – Underground Fuel storage tank failure

- Fuel storage tanker installation failed fuel line disconnected
- Fuel leak Environmental contamination
- Preventative measures not in place
- Environmental pollutants could not be contained
- Damage assessment
  - Storage tank inspected
  - Maintenance procedures not followed

![](_page_29_Picture_9.jpeg)

![](_page_29_Picture_10.jpeg)

#### What could have been done?

- Preventative measures
- Environmental impact study = Test plan
- Sampling of soil and surrounding water sources

Laboratory testing

**Detectable sources of contamination** 

- Oil in water
- Ground water contamination (pH, TOC)
- Chemical action
- Lubricants
- Tribology analysis (Petrochemical)
- Metal contaminants (Hg, Cr etc.)

![](_page_30_Picture_12.jpeg)

#### Case study – Acid spill from tanker

- Scenario Tanker liner failure
- Initial on-site thermal analysis Identified correct sampling areas
- Sample was removed and analysed using Physical testing

![](_page_31_Picture_4.jpeg)

![](_page_31_Picture_5.jpeg)

#### Case study – Acid spill from tanker

![](_page_32_Picture_1.jpeg)

- Coating was not soluble in HCl
- Microscopic investigation indicated four distinct and uneven layers
- Polymerisation inefficient
- Product application was done incorrectly

#### Case study – PCB Failure

- Scenario Claim for lightning damage
- Visual investigation PCB visibly damaged

![](_page_33_Picture_3.jpeg)

![](_page_33_Picture_4.jpeg)

### Case study – PCB Failure

![](_page_34_Picture_1.jpeg)

64

### Case study – PCB Failure (Lightning)

![](_page_35_Picture_1.jpeg)

![](_page_35_Picture_2.jpeg)

![](_page_35_Picture_3.jpeg)

#### Case study – PCB Failure

- Scenario Claim for lightning damage on Inverter
- Visual investigation Ingress

![](_page_36_Picture_3.jpeg)

![](_page_36_Picture_4.jpeg)

![](_page_36_Picture_5.jpeg)

#### Case study – PCB Failure

- Scenario Claim for lightning damage on Inverter
- Visual investigation Ingress

![](_page_37_Picture_3.jpeg)

![](_page_37_Picture_4.jpeg)

#### Case study PCB - lightning vs. surge

- Scenario lightning or surge
- Microscopy and Scanning Electron Microscope (SEM) was used to investigate the board

![](_page_38_Picture_3.jpeg)

#### Case study PCB - lightning vs. surge

• Characteristic lightning patterns was absent and damage consistent with control sample, where power surge caused boards to ignite

![](_page_39_Picture_2.jpeg)

![](_page_39_Picture_3.jpeg)

### Case study PCB - lightning vs. surge

![](_page_40_Picture_1.jpeg)

![](_page_40_Picture_2.jpeg)

![](_page_40_Picture_3.jpeg)

![](_page_40_Picture_4.jpeg)

![](_page_40_Picture_5.jpeg)

Lightning pattern

Corrosion pattern

#### Solar Battery Installation-Investigation

- Thermal imaging
- Electronic investigation

![](_page_41_Picture_3.jpeg)

![](_page_41_Picture_4.jpeg)

![](_page_41_Picture_5.jpeg)

![](_page_41_Picture_6.jpeg)

![](_page_41_Picture_7.jpeg)

#### Solar Battery Installation- Battery assessment

#### • Postmortem assessment

![](_page_42_Picture_2.jpeg)

#### Solar Battery Installation- Battery assessment

• Postmortem assessment

![](_page_43_Picture_2.jpeg)

![](_page_43_Picture_3.jpeg)

![](_page_43_Picture_4.jpeg)

#### Solar Battery Installation- Battery assessment

- Laboratory assessment
  - Specific gravity
  - pH
  - Ionic composition

![](_page_44_Picture_5.jpeg)

![](_page_45_Picture_0.jpeg)

#### **Reporting – Factual evidence**

- Preliminary assessment
- Recommendation on the correct procedure and initial testing
- Advanced Laboratory testing
- A formal report will be compiled stating all the Analytical results and facts (approved by an Analytical Chemist)
- Possible cause and **conclusion will be highlighted**
- Short summary of outcome with photographic evidence will be supplied
- **Record keeping** for future reference and evidence (as per requirement)

![](_page_46_Figure_0.jpeg)

#### **Pre-Loss (Risk assessments)**

# We assist by helping to identify potential faults before they become problems

- Lightning and power surge protection
- PV (Solar) installation verification
- Surveys for laboratories and businesses

![](_page_46_Figure_6.jpeg)

![](_page_47_Figure_0.jpeg)

#### **Lorca Consulting**

- Where we are
  - Solid network of professionals in the relevant industries
  - Skilled team able to offer a complete solution
  - Scientific facts to back up our assessments and reports

![](_page_48_Picture_0.jpeg)

# Thank you!